

Evita 4

Technical Service Bulletin # 33

Re:	Modified / new test cable for electrical safety test		
Update:	May 22, 2000		
Reference Doc:	IDM no. 33 / 06.99		
Reason:	The test cable P/N 79 10 393 with 9pin SUB-D connector for electrical safety test must be modified due to a change in the design of the CPU PCB.		
Solution:	<p>Short term solution:</p> <p>Remove pins 5 and 7 on 9-pin SUB-D connector of P/N 79 10 393. This can be accomplished with curved snipe nose pliers. Position pliers at lowest possible point of one pin and remove pin by moving pliers back and forth several times. Repeat procedure for second pin.</p> <p>Long term solution:</p> <p>Replace current version with SUB-D connector P/N 79 10 393 with the new version with an AWT (Airway Temperature) connector P/N 79 10 364. This version will available as of July 2000. This new version can also be used on Evita 2 dura and Evita.</p>		
Devices affected:	All test cables with 9pin SUB-D connector P/N 79 10 393 for Evita 4 and Evita 2 dura.		
When:	Effective immediately		
Additional Info:	N/A		
Cost:	Covered by User of test equipment		
Ordering Info:	Shorting plug AWT connector (available as of July 2000)		P/N 79 10 364
Distribution:	Dräger Service Personnel and Authorized Service Organizations for CCS products.		

If you have any questions, please contact Technical Support by phone at 1-800-543-5047 or by fax at 1-215-721-5789

Dräger Medical, Inc.
Technical Product Manager